

# THE STATE OF NEW HAMPSHIRE DEPARTMENT OF TRANSPORTATION



William Cass, P.E. Assistant Commissioner

Victoria F. Sheehan Commissioner

His Excellency, Governor Christopher T. Sununu and the Honorable Council State House Concord, New Hampshire 03301 Bureau of Highway Maintenance July 28, 2022

## **REQUESTED ACTION**

Authorize the Department of Transportation to retroactively pay Chappell Tractor (Vendor No.154240) of 391 Loudon Road, Concord NH, in the amount of \$5,276.19, for repair work performed on New Holland Tractor H-1817, effective upon Governor and Council approval. 100% Highway Funds.

Funds to support this request are available in the following account for FY 2023:

FY 2023

04-96-96-960515-3007 Highway Maintenance Bureau 020-500235 Vehicle Maintenance

\$5,276.19

### **EXPLANATION**

The item is **retroactive** because the vendor did not submit the invoice request in a timely manner upon completion of work. H-1817 is a NHDOT-owned 2006 New Holland TL90A four-wheel drive tractor outfitted with a side-mounted mower. It developed mechanical issues needing repairs by a qualified mechanic in June 2021 and was last used June 10, 2021. It was transported to Chappell Tractor on Loudon Road in Concord on July 13, 2021, for repairs. Chappell Tractor is an authorized New Holland dealer.

There were two significant issues: leaking air conditioning lines and the rear differential lock in the transmission. When Chappell Tractor diagnosed the issues, it was determined that the air conditioning lines needed to be replaced. One of the lines was on backorder for several months. Repairs were completed with no further consultation with NHDOT District 3 as to cost of repairs. Total cost of this portion of repairs was \$1,289.55.

Similarly, repairs to the transmission occurred without further consultation with NHDOT District 3 as to estimated cost. Service technicians diagnosed the issue as a stick going between the fuel tank and the transmission, "disrupting the solenoids for the differential lock". In the process of resolving the issue the cost of parts totaled \$484.91, and labor \$3,302.00.

The Chappell Tractor Equipment Service Manager notified our welder mechanic in Fall 2021 that the repairs had been completed, but no invoice was submitted for payment until March 28, 2022. We believe changes in personnel at Chappell Tractor may have contributed to these further delays. Included on the invoice with the above subtotals was a miscellaneous shop parts charge of \$35.52 and a Shop Supplies charge of \$164.21, bringing the combined invoice total to \$5,276.19.

The Department of Transportation is responsible for mowing shoulders and slopes along State highways to maintain sight distance from side roads and driveways and to inhibit the growth of trees on slopes. We do so with a combination of State-owned and rented equipment. Maintenance of State-owned tractors is generally accomplished by in-house employees, but in this case, the scope and complexity, was beyond our capabilities.

The tractor remains parked at Chappell Equipment pending payment of this invoice.

Sincerely,

Victoria F. Sheehan Commissioner

Attachments



391 Loudon Rd Concord, NH 03301 (603) 225-3381 www.chappell.com

Ship To: 'IN STORE PICKUP

Dept 22 Account

Invoice To: STATE OF NH DOT DISTRICT #3-2 SAWMILL RD. GILFORD NH 03249

'Branch				
CONCORD				
Date	Time			Page
03/28/22	13:	06:31 (0)		01
Account No	Phone No	)	Inv	No
NHDOT015	603	5246667	WO	0,065
Ship Via		Purchase Orde	7	
Tax ID No				
		Sal	espers	วุก
			js	

#### **SERVICE INVOICE**

STK#/FLEBT#

HRS PIN/BIN

WARRANTY DATE

HRS

E000634

tractor TL90A 2 HJS072706 F4CE0454E

07/15/21 07/16/21

SEGMENT# 1 C 1080 NA A/C line leaking

COMPLAINT:

Customer requests we replace both a/c lines and charge the system. Test operation after repairs. Brandon 344-0808 CORRECTION:

Replaced one of the A/C lines that went to the evaporator. One line was on back order for over a year. Pulled vacuum and charged the system to see if we could find the leak. Found a leak in a different hose. This hose was zip tied to a bracket and due to that it wore a hole in the line. Replaced that line. Pulled vacuum and charged the system, operated the system and verified the repair. No additional leaks were found.

IN	FREIGHT IN 23.10	23.10
47129953	HOSE RETAIL 297.00	
•	1 N 270,00	270.00
47129955	HOSE 1 N 193.00	19300
	PARTS	486.10
	LABOR	803.45
.1:1.10000Õ	SEGMENT TOTAL ==>	1289.55

SEGMENT# 2 C 1080 NA

07/15/21 09/14/21

rear diff lock

COMPLAINT:

Customer states that the rear diff lock is inop. Can hear a click noise but does not lock in and does not show locked in on the monitor. Brandon 344-0808
CAUSE:

CONTINUED ON PAGE 02

Any warranties on the products told hereby are those made by the manufacturer. The Seler, hereby expressly disclosine as warranties, either express or implied, including any implied warrantly of merchantability or fitness for a particular pulpose, and neither essumes nor authorizes any other person to assume for it any, intigly in connection with the sale of tabl products. All accounts 30 days past due are subject to 1,5% service charge per mich. This subject to 1,5% per sinium. All accounts described by self-become C.O.D. status. Specially profered parts will not be accepted for return. All accepted for return to be paid in advance, No refunds or exchanges on electronic components or fuel system parts. All claims and returned goods must be accompanied by this invoice.

Racely	-4.3

Thank You For Your Business!



391 Loudon Rd Concord, NH 03301 (603) 225-3361 www.chappell.com

Ship To: IN STORE PICKUP

Involce To: STATE OF NH DOT DISTRICT #3 2 SAWMILL RD. GILPORD NH 03249

Branch					
CONCORD					
Date	Time			Page	
03/28/22	13:	06:31 (0)	)	0.2	
Account No	Phone No	Phone:No		Iny No	
NHDOT015	603	6035246667		W00065	
Ship Via	Ship Via		et,		
Tex ID No	<u> </u>			<u> </u>	
		Si	lesper	ióu	
			JS		

#### **SERVICE INVOICE**

STR#/FLEET#

11100000

HRS PIN/EIN

WARRANTY DATE

HRS

R000634

tractor TL90A

2 HJ8072706

F4CB0454B

FOUND A STICK HAD CONE UP THUR UNDERNEATH BETWEEN FUEL TANK AND THE REAR AXLE, DISRUPTING THE SOLENOIDS FOR THE DIFFERENTIAL LOCK. ALSO SWITCH WAS NOT WORKING IN DASH. REPLACE SWITCH BUT THE LIGHT ON STILL WILL NOT TURN ON. REMOVED THE SWITCH ON THE REAR END FOR TURNING ON LIGHT ON CLEANED AND TESTED. TRACED WIRING ALL THE WAY TO THE FIREWALL CONNECTORS EVERYTHING TESTED GOOD TO THERE. HOOKED UP LAPTOP, RAN THRU PROGRAM CLEARED ALL: FAULT CODES CREATED BY UNPLUGGING WIRING HARNESSES AND TESTING. NO FAULT CODES CAME BACK. SCHEMATIC SHOWS THE ALSO GOING INTO THE ECU , ... CLUSTER AND MODULE. THE PROBLEM COULD BE IN THE BOU, A MODULE OR IN THE WIRING HARNESS WHICH HAS BEEN JUMPED INTO.

THE DIFFERENTIAL LOCK SWITCH IS NOW WORKING LIKE IT SHOULD. 2

THE LIGHT ON THE DASH IS STILL INOP, IN FREIGHT IN O-RING-NR 14453081

14453283 O-RING WASHER SEALING 5178210 SWITCH, DIFF LO 5184399 2.5G MSTR/TRAN 73341773 HOSE, FLEXIBLE 87577321

> LABOR SEGMENT TOTAL ==>

10 N

2: N

10 N

I. N 1

1 N

67.11 14.00 12,80 22.50 33.50

> 55:.00 280 .00 484.91 3302.00

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS.

33,56

6,40 2.25

33.50

280.0Ó

55.00

PARTS.

1.40

971.01

3786.91

CONTINUED ON PAGE 03

Received By

Any warrantes, on the products soid nereby are those made by the manufacturer. The Setter frejety expressly disclaims as warranties, either express or impaid, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. All accounts 50 days past due are subject to 1,6% service charge per month. This is at the rate of 18% per annum. All accounts past 60 days will become C.O.D status. Specially ordered parts will not be accepted for rature.

All special-order theme to be paid in edylange, No refunds or exchanges on electronic components or fuel system parts. All dispresent refunds or exchanges on electronic components or fuel system parts. All dispresent refunds or exchanges on electronic components or fuel system parts.

Thank You For Your Business!



391 Lougon Rd Concord, NH 03301 (603) 225-3361 www.chappell.com

Ship To: IN STORE PICKUP

Invoice To: STATE OF NH DOT DISTRICT #3

2 SAWMILL RD. GILFORD NH 03249

Branch					
CONCORD Date 03/28/22	Time 13:	06:3i (		Page .03	
Account No NHDOTO15	Phone No	Phone No 6035246667		Inv No W00065	
Ship Via			urchase Order		
Tax.ID. No					
		<u> </u>	Sąlespera	son	
			Salesperzon JS		

## **SERVICE INVOICE**

STK#/FLEET#

E000634:

tractor

TL90A

HRS PIN/RIN 2 HJ8072706

P4CB0454B

WARRANTY DATE

HRS

 LABOR
 4105.45

 MISC SHOP PARTS
 35.52

 SHOP SUPPLIES
 164.21

 IN HOUSE CHARGE
 5276.19

Any warmstee on the products well hereby, are those made by the manufacturer. The deter hareby expressly dischline at warmsties, either express or implied, including any implied warmstry of merchantatility or fitness for a particular pulpose, and nather assumes not sufferings any other perion to essume tonit by implied by in connection with the sale of said products. All accounts 30 days paid due are subject to 1.5% service charge paymonth. This is at the pate of 16% per annum. All spoounts past 50 days will become C.O.D strate. Specially proteined participal on the accepted for return.

All special-order larms to be paid in advance. No returned or exchanges on electronic components or fuel system parts. All tileims and returned goods must the accompanied by this invoice.

Received By

Thank You For Your Business!