



STATE OF NEW HAMPSHIRE  
 DEPARTMENT of CULTURAL RESOURCES  
*State Council on the Arts, Division of Historical Resources  
 State Library, Film & Television Office,  
 Commission on Native American Affairs (administratively attached)*



20 Park Street  
 Concord, New Hampshire 03301

VAN McLEOD  
 Commissioner  
 Van.McLeod@dcr.nh.gov

TEL: 603-271-2540  
 FAX: 603-271-6826  
 www.nh.gov/nhculture

January 7, 2016

Her Excellency, Governor Margaret Wood Hassan  
 And the Honorable Council  
 State House  
 Concord, NH 03301

Retroactive

REQUESTED ACTION

The Department of Cultural Resources, New Hampshire State Library, requests permission to make a retroactive unencumbered payment in the amount of \$11,055.03 to Grappone Collision Center, Bow, NH (vendor code 158740 ) for the repair of a 2015 Ford Transit Cargo Van, effective upon Governor and Council approval.

100% Federal Funds

Funds are available in the account titled Federal Library Programs as follows:

	<u>FY 2016</u>
01-34-340510-71800000-020-5000235 Current Expense	\$11,055.03

EXPLANTION

This request is retroactive as last minute cost overages brought the total above the amounts requiring Council limits.

New Hampshire State Library's van delivery service facilitates the exchange of inter-library loan materials between New Hampshire public libraries. Four vans travel on pre-determined routes across the state on a daily basis. On the morning of September 17<sup>th</sup> LB 8, a 2015 Ford Transit Cargo Van, was involved in a collision with a moose. Although damage to the vehicle was extensive, the driver did not sustain any injuries. The vehicle was towed to Grappone Collision Center and we received an estimate of \$9,964. Grappone was given permission to start the work. As repairs progressed we were notified by Grappone that additional damages had been found. As labor and material costs had already been incurred Grappone was given permission to proceed with the repairs.

Respectfully submitted

Van McLeod  
 Commissioner



# GRAPPONE COLLISION CENTER

## FINAL BILL SUPPLEMENT

nh stat  
Estimate 15028  
Repair Order 53479

FINAL BILL SUPPLEMENT SUMMARY			
New (OEM) Parts:	\$1,582.01		
Other parts:	\$29.95		
	Units	Rate	Amount
BODY/HEAVY	: 3.4	\$48.00	\$163.20
RATE CHANGES			
			Sublet: \$312.00
			Parts Total: \$1,611.96
			Labor Total: \$163.20
			Body/Material: \$12.00
			Total: \$2,099.16
CUSTOMER PAY PAYABLE SUPPLEMENT TOTAL			\$2,099.16

Labor Dept Codes: B-BODY/HEAVY D-ASSEMBLE I-SUBLET E-WASH F-FRAME G-RETAIL CLEAN M-MECHANICAL P-PAINT S-RP  
 PT - Price Types: O - New (OEM); A - New (Non-OEM); V - Used Parts; R - Reconditioned; Space - No Type  
 L - Labor; M - Material; H - Hazardous; S - Storage; T - Towing; U - Sublet  
 BT - Billing Types: No Code - Insurance Charge; CC - Customer Charge; BT - Betterment; AP - Appearance Allowance  
 PD - Prior Damage; NC - No Charge

CCC One Data, Copyright 1995 CCC Information Services (\*) Indicates Estimator Judgement.

The elements of data used to calculate this Estimate were obtained from a CCC Database.

Calculations of the Estimate are performed by a computer program created by YADA Systems, Inc.

ProfitNet [Ver. 10.00.2927] © 1989-2014 YADA Systems, Inc. All rights reserved. Licensed by GRAPPONE COLLISION CENTER

# GRAPPONE COLLISION CENTER

Page 1  
 Printed 12/01/2015 3:17 PM  
 Created 09/29/2015

**FINAL BILL**  
 506 STATE RTE. 3A  
 BOW, NH 03304  
 (603) 226-8075 FAX: (603) 224-0681  
 WWW.GRAPPONE.COM

nh state library  
 Estimate: 15028  
 Repair Order: 53479

<b>Customer: Insured</b> nh state library 20 park st concord, NH 03301 Work: (603) 271-2401	<b>Vehicle:</b> FORD T150 TRANSIT LOW CARGO 1; YEAR: 2015 Color: white Paint Code: YZ License: LB8 NH Prod Date: 05/01/2015 Mileage In: 10918 VIN: 1FTNR2YM6FKB00633 Sched. Arrival Date: 09/22/2015 Arrival Date: 09/22/2015 Proj. Delivery Date: 11/10/2015 Billed Date: 11/30/2015 Delivery Date: 11/30/2015 Drivable: Unknown	<b>Ins. Company:</b> CUSTOMER PAY Claim Number: CUSTOMER PAY
---	---	--

Written by: COLLUPY, RICK	Price	Ext. Price	Labor Units	Paint Units	PT	BT
Item						
1 *** VISUAL DAMAGE ONLY***						
2						
3 FRONT BUMPER & GRILLE						
4 OVERHAUL O/H bumper assy			3.0 B			
5 REMOVE/REPLACE Grille w/o chrome	347.48	347.48	Incl.		O	
6 REMOVE/REPLACE Bumper cover	450.15	450.15	Incl.	2.8	O	
7 REMOVE/REPLACE Bumper Core						
8 Add for Clear Coat				1.1		
9 REMOVE/REPLACE Reinf panel	223.85	223.85	Incl.		O	
* 10 REMOVE/REPLACE Ornament	*		Incl.		O	
11 REMOVE/REPLACE Bumper cover retainer	2.18 (6)	13.08			O	
13 REMOVE/REPLACE Bumper Core						
14 FRONT LAMPS						
15 REMOVE/REPLACE RT Headlamp assy w/o chrome trim	668.02	668.02	Incl.		O	
17 Aim headlamps			0.5 B			
18 REMOVE/REPLACE LT Headlamp assy w/o chrome trim	668.02	668.02	Incl.		O	
20 RADIATOR SUPPORT						
21 REMOVE/REPLACE Mount panel	897.10	897.10	2.5 B	1.8	O	
22 REMOVE/REPLACE RT Upper bracket	14.35	14.35	0.2 B	0.2	O	
23 Add for Clear Coat				0.1		
24 REMOVE/REPLACE LT Upper bracket	14.35	14.35	0.2 B	0.2	O	
25 Add for Clear Coat				0.1		
26 COOLING						
27 REMOVE/REPLACE Radiator	578.48	578.48	2.5 B		O	
28 REMOVE/REPLACE Fan & motor	168.60	168.60	Incl.		O	
29 REMOVE/REPLACE P/S cooler	147.78	147.78	0.5 B		O	
* 30 REMOVE/REPLACE P/S cooler bracket	*		Incl.		O	
* 31 REMOVE/REPLACE Coolant (Ford Gold) (VC7B)	16.71 (2)	33.42			O	
34 AIR CONDITIONER & HEATER						
35 REMOVE/REPLACE Condenser	199.95	199.95	1.0 B		O	
36 AC Service evacuate & recharge			1.4 B			
37 AC Service refrigerant recovery			0.4 B			
38 HOOD						
39 REMOVE/REPLACE Hood	818.80	818.80	1.2 B	2.0	O	
40 Add for Clear Coat				0.8		
41 Add for Underside(Complete)				1.0		
42 REMOVE/REPLACE Front seal	29.77	29.77	0.2 B		O	
43 REMOVE/REPLACE LT Vent grille	84.43	84.43	Incl.		O	

# GRAPPONE COLLISION CENTER

## FINAL BILL

Written by: COLLUPY, RICK

Item	Price	Ext. Price	Labor Units	Paint Units	PT	BT
44 REMOVE/REPLACE RT Vent grille	68.57	68.57	Incl.		O	
45 REMOVE/REPLACE Insulator 3.7 liter	147.98	147.98	Incl.		O	
* 46 REMOVE/REPLACE Latch w/ anti theft	107.07	107.07	Incl.		O	
* 48 REMOVE/REPLACE Insulator retainer clip					O	
49 REMOVE/REPLACE LT Hinge	61.18	61.18	0.3 B	0.3	O	
50 Add for Clear Coat				0.1		
51 REMOVE/REPLACE RT Hinge	64.70	64.70	0.3 B	0.3	O	
52 Add for Clear Coat				0.1		
53 FENDER						
54 REMOVE/RE-INSTALL RT R&I fender assy			1.3 B			
55 REMOVE/RE-INSTALL LT R&I fender assy			1.3 B			
56 REPAIR RT Fender			1.0 B	2.0		
57 Overlap Major Adj. Panel				-0.4		
58 Add for Clear Coat				0.3		
59 REPAIR LT Fender			1.0 B	2.0		
60 Overlap Major Adj. Panel				-0.4		
61 Add for Clear Coat				0.3		
62 REMOVE/RE-INSTALL RT Wheel opng mldg			Incl.			
63 REMOVE/RE-INSTALL LT Wheel opng mldg			Incl.			
64 REMOVE/RE-INSTALL RT Upper molding w/o dual rear wheels			Incl.			
65 REMOVE/RE-INSTALL LT Upper molding w/o dual rear wheels			Incl.			
66 REMOVE/REPLACE RT Upper molding clip					O	
67 REMOVE/REPLACE LT Upper molding clip					O	
68 REMOVE/RE-INSTALL RT Fender liner			Incl.			
69 REMOVE/RE-INSTALL LT Fender liner			Incl.			
70 ELECTRICAL						
71 REMOVE/REPLACE Antenna mast	26.64	26.64	0.1 B		O	
* 72 REMOVE/REPLACE Antenna cable w/o navigation					O	
73 REMOVE/RE-INSTALL RT Base			0.5 B			
74 WINDSHIELD						
* 75 REMOVE/REPLACE Windshield FORD, w/mirror, w/o rear came	342.50	342.50	3.5 B		O	*
* 76 SU GLASS KIT	21.80	21.80			M	*
83 ROOF						
* 84 REPAIR Front roof pnl w/o HD radio			1.0 B		*	
* 85 Overlap Major Non-Adj. Panel					*	
* 86 Add for Clear Coat					*	
* 87 Add for Inside					*	
* 88 REMOVE/RE-INSTALL Front headliner w/o rear park aid						
* 89 BLEND RT ROOF RAIL				0.5	*	
* 90 BLEND LT ROOF RAIL				0.5	*	
91						
* 92 CAR COVER- REFINISH	5.00	5.00	0.3 B		M	*
* 93 CAR COVER-PRIMER	5.00	5.00	0.3 B		M	*
94 TINT COLOR TO MATCH				0.5		
95 HAZARDOUS WASTE REMOVAL	5.00	5.00			H	
96 DENIB & BUFF			2.0 B			
* 97 REMOVE/REPLACE CORROSION PROTECTION	15.00	15.00	0.3 B		M	*
* 98 REMOVE/REPLACE SEAM SEALER	48.00	48.00			M	*
* 99 REMOVE/REPLACE ROOF PANEL ADHESIVE KIT					M	*
100 REPAIR COVER INTERIOR			0.4 B			
101 BROKEN GLASS CLEAN UP			1.0 B			
102 SU tow bill / brc towing	95.00	95.00			U	

# GRAPPONE COLLISION CENTER

## FINAL BILL SUPPLEMENT

506 STATE RTE. 3A

BOW, NH 03304

(603) 226-8075 FAX: (603) 224-0681

WWW.GRAPPONE.COM

nh state library

Estimate: 15028

Repair Order: 53479

Page 1  
Printed 12/01/2015 3:17 PM  
Created 09/29/2015

<b>Customer: Insured</b>  nh state library 20 park st concord, NH 03301 Work: (603) 271-2401	<b>Vehicle:</b>  FORD T150 TRANSIT LOW CARGO 1: YEAR: 2015 Color: white Paint Code: YZ License: LB8 NH Prod Date: 05/01/2015 Mileage In: 10918 VIN: 1FTNR2YM6FKB00633 Sched. Arrival Date: 09/22/2015 Arrival Date: 09/22/2015 Proj. Delivery Date: 11/10/2015 Delivery Date: 11/30/2015 Drivable: Unknown	<b>Ins. Company:</b>  CUSTOMER PAY Claim Number: CUSTOMER PAY
---	--	--

Item	Extended Parts Prices			SG	Dpt	Labor Units			PT	BT
	Estimated	Actual	Diff			Est	Act	Diff		
12 REMOVE/REPLACE Lower cover gray		297.22	297.22	1A			Incl.		O	
16 REMOVE/REPLACE Lamp Core		50.00	50.00	1A						NC
19 REMOVE/REPLACE Lamp Core		50.00	50.00	1A						NC
* 32 REMOVE/REPLACE Coolant (Ford Gold) (VC7B)	33.42	44.70	11.28 (2)	1A					O	
33 REMOVE/REPLACE Overflow hose from 1/09/15		22.44	22.44	1A					O	
* 47 REMOVE/REPLACE Latch w/ anti theft	107.07	120.28	13.21	1A					O	
77 REMOVE/REPLACE Wiper linkage		86.00	86.00	1A	B		0.3	0.3	O	
* 78 REMOVE/REPLACE Wiper linkage	86.00	96.38	10.38	1A					O	
79 REMOVE/REPLACE RT Wiper blade		17.48	17.48	1A	B		0.1	0.1	O	
* 80 REMOVE/REPLACE RT Wiper blade	17.48	12.48	-5.00	1A					O	
81 REMOVE/REPLACE LT Wiper blade		17.48	17.48	1A	B		0.1	0.1	O	
* 82 REMOVE/REPLACE LT Wiper blade	17.48	12.48	-5.00	1A					O	
103 REPAIR HEATER VENT				1A	B		1.0	1.0		
* 104 REMOVE/REPLACE pwr steering fluid		12.00	12.00	1A						M
105 REMOVE/REPLACE THROTTLE BODY		394.68	394.68	1A	B		1.0	1.0	O	
* 106 REMOVE/REPLACE THROTTLE BODY GASKET				1A					O	
107 REMOVE/REPLACE THROTTLE BODY PLUG		62.68	62.68	1A	B		1.0	1.0	O	
108 ENGINE				1A						
109 REMOVE/REPLACE LT Valve cover		73.48	73.48	1A					O	
110 REMOVE/REPLACE Inlet duct		12.17	12.17	1A	B		0.1	0.1	O	
* 111 REMOVE/REPLACE air mass plug				1A						
112 COWL				1A						
113 REMOVE/REPLACE Cowl vent panel		267.52	267.52	1A	B		1.0	1.0	O	
114 REMOVE/REPLACE RT Fender Moulding		39.40	39.40	1A					O	
115 REMOVE/REPLACE LT Fender Moulding		39.40	39.40	1A					O	
116 SUBLET Install Windshield		80.00	80.00	1A	B		-1.6	-1.6	U	
117 REMOVE/REPLACE Duct		5.05	5.05	1A					O	
118 REMOVE/REPLACE A/C Label w/ Freight		29.95	29.95	1A						A
119 REMOVE/REPLACE Hose		73.28	73.28	1A	B		0.2	0.2	O	
120 REMOVE/REPLACE Striker		48.40	48.40	1A					O	
121 REMOVE/REPLACE Prop Rod Clip		2.00	2.00	1A					O	
122 REMOVE/REPLACE Plate Bracket		49.92	49.92	1A	B		0.2	0.2	O	
123 REMOVE/REPLACE LT Cowl Side Panel		24.27	24.27	1A					O	
124 REMOVE/REPLACE RT Cowl Side Panel		24.27	24.27	1A					O	
125 SUBLET Replace Valve Cover		147.00	147.00	1A						U
126 SUBLET tow charge/ no start		85.00	85.00	1A						U